

The importance for keeping your Oxygen Odouriser working correctly is a high priority on any site to ensure the health and safety of the workforce and HSE compliance. Paladon Systems offer a comprehensive Oxygen Odouriser service that we strongly recommend is performed every 12 months.

The comprehensive service package includes:

- Charcoal canister replenished
- Fomblin fluid canister level checked and topped up as necessary
- DMS tank inspected for integrity and any signs of leakage from the fill ports/level gauge
- Dosing pump inspected and checked for correct operation, including dosing check valves
- DMS check valve inspected, sealing washer renewed and then checked for correct operation
- Flow meter inspected and checked for correct operation
- Oxygen pipeline bypass valves inspected and checked for correct operation
- Control cabinet inspected. All components checked they are working as per design
- All fittings and fixings are inspected
- After the service the system is run to check the dosing levels are correct for the flow of oxygen. A Drager test will be carried out to check the DMS levels in the oxygen at the furthest point on site



Paladon Systems will advise if any parts on the Oxygen Odouriser are in need of replacing urgently or make a suggestion that on the next visit it would be advisable for them to be replaced at that time.

Contact us today at 01604 880700 or [info@paladonsystems.com](mailto:info@paladonsystems.com) to find out how we can protect your people and equipment.